


Building Inspection
 For Indland Mtg. Co.
 Being lots 127 & 128 of John Rings
 4th Addition to the village of
 West Unity Wm.s Co. Ohio
 Grantor James Gorsuch Grantee Richard B. Carrothers



o Found 1/2" Iron Pin
 X Found X in conc. walk

Ref. to survey dated May 12 1977
 by Basselman & Aschemeier Eng. & Surveying

The improvements in the above described real estate are not in the 100 year flood plain as shown on the flood maps prepared by the Department of Housing and Urban Development; therefore flood insurance shall not be required by Federally insured lending institutions.

I hereby certify that I have surveyed the premises and prepared the above plat and that said plat is correct to the best of my knowledge and belief. All dimensions are shown in feet and decimal parts thereof. This survey has been recorded in Vol. 5V page 229 of the Williams County Record of Surveys.

NOTE: This mortgagee's inspection was prepared for identification purposes for the mortgage, and is not intended or represented to be a land or property line survey. No corners were set. Do not use for establishing fence or building lines. No responsibility is extended herein to the land owner or occupant.

Lawrence R. Erikson
 Reg. Surveyor #6391