
## PLAT & SURVEY

LOCATED IN THE SOUTHEAST QUARTER, SECTION 12, T-6-N, R-2-E, CENTER TOWNSHIP, KNOWN AS LOT 74 OF NORLICK PLACE SUBDIVISION 3rd ADDITION, WILLIAMS COUNTY, OHIG.

> FOR CITIZENS NATIONAL BANK WESLEY & GERALDINE BARRY BUYER SELLER DENNIS & KAY LASH

- FOUND DAMAGED IRON PIN, PLACED 5/8" REBAR O FOUND IRON PIN OR PIPE
- PLACED 5/8" REBAR (R) RECORDED DIST. (M) MEASURED DIST. OA FOUND DAMAGED IRON PIN 0.57'N



The improvements in the above described real estate are not in any flood hazard area (Zone A) as shown on the Flood Hazard Boundary Map as published by U.S. Department of Housing and Urban Development, Therefore, flood Community Panel No. 390580 A 390580 A be required by Panel Community funded lederally insurance" will not

I hereby certify that I have surveyed the premises and prepared the above and that said plat is correct to the best of my knowledge and belief.

A dimensions are shown in feet and decimal parts thereof. This survey has been recorded in Vol. 1012 Page 273 of the Williams County Record of Surveys.

DENNIS

BELL 6717

PEGISTERED

SURVEYC

SCALE: 1" = 20'

DATE: 7/11/86 JOB NO.: OS - 130 - 8

Dennis M. Bell Reg. Surveyor #6717

BELL ENGINEERING LIMITED W. HIGH - PO. BOX 865 1211 43506 OHIO 636 - 2585 (419)