

Plat of Survey

Being a part of the Northwest quarter (1/4) of Section 29, Township 6 North, Range 1 East, St. Joseph Township, Williams County, Ohio.

Co. Rd. C

For... Gene & Ethel Partin

Vol. 270 Pg. 597

Legend

- A- Railroad spike found.
- B- PK nail found.
- C- Iron pin found.
- D- 5/8" x 30" ID capped Iron pin set.
- E- PK nail set.




Northeast Corner
Northwest Qtr.
Section 29

733.98 Meas.

Co.-Rd.-2-50

East line Northwest Qtr.



I do hereby certify that I surveyed the premises and prepared the above plat and that said plat is correct to the best of my knowledge and belief.

All dimensions are shown in feet and decimal parts thereof.
This survey has been recorded in Volume 17R, Page 237,
of the Williams County Record of Surveys.

Thomas J Henry
Registered Surveyor No. 6787
August 18, 198

Southeast Corner
Northwest Qtr.