

PLAT OF SURVEY

BOUNDARY RETRACEMENT SURVEY

Located In The Northwest Fractional Quarter And The Northeast Fractional Quarter Of Section 3, Town 6 North, Range 2 East, North & East Of The First Principal Meridian And Base Line, Center Township, Williams County, Ohio

Prepared For: Rich Smethurst
 Survey Conducted: February 2018

- Description Of Monuments**
- A. Found PK Nail
 - B. Found MAG Nail
 - C. Found Iron Pin
 - D. Found 5/8" Rebar
 - E. Found 5/8" Rebar w/ ID Cap "HOEFFEL"
 - F. Found 5/8" Rebar w/ ID Cap "WIELAND" (2.29' South of E-W 1/4 Line)
 - G. Found 3/4" Iron Pipe w/ Cap "K&K/LIMA"
 - H. Found 8"x6" Wood Post
 - I. Set 5/8" Rebar w/ ID Cap
 - J. Set 5/8" Rebar w/ ID Cap at best fit intersection of wire fences and at base of rotted off wood post - Center of Section 3
 - K. Set MAG Nail
 - L. Point Established
 - M. Point Established in Centerline of Ditch

Note:
 Rebars called for as Set are 5/8" Dia., 30" long, set 3" above ground (unless otherwise noted) and capped with yellow plastic cap inscribed "KRUEGER/PS 8572".

- Reference Surveys:**
- Vol. 6R, Pg. 169
 - Vol. 7R, Pg. 130
 - Vol. 9R, Pg. 208
 - Vol. 10R, Pg. 234
 - Vol. 16R, Pg. 224
 - Vol. 20R, Pg. 190
 - Vol. 26R, Pg. 44

Reference Plans: WIL-C.R. 27 (G), Right Of Way Plans - 2002

BASIS OF BEARINGS:
 The bearings shown hereon are based on an assumed bearing and are for the sole purpose of showing angular measurement.

NOTE:
 This survey does not include a title search, thus there could be easements on this property that are not shown on this plat.

CERTIFICATION:
 I hereby certify that this plat represents a survey made by me and that it is correct to the best of my knowledge and belief. All dimensions are shown in feet and decimal parts thereof.

Dexter A. Krueger
 Dexter A. Krueger, P.S.
 Ohio Professional Surveyor No. S-8572

03/31/2018
 Date

