
PLAT OF SURVEY Fland situated in the Southeast Quarter of Section 3. To

A parcel of land situated in the Southeast Quarter of Section 3, Town 10 South, Range 4 West, Northwest Township, Williams County, Ohio. Located within the Michigan Meridian Survey of the Original Land Subdivisions of Ohio.



SURVEY LEGEND

- Placed 5/8" Rebar w/ Cap
- X Found PK Nail
- ● Point Established this Survey
 - O Found Iron Pin or Pipe

REFERENCE SURVEYS

Volume 8R Page 166 Volume 25R Page 101

GENERAL OCCUPATION NOTE:

Random broken fence existed along portions of the North boundary of this property. The Western boundary was wooded & agricultural.

I HEREBY CERTIFY THAT I HAVE SURVEYED THE PREMISES SHOWN OF THE PLAT ABOVE. ALLO DIMENSIONS ARE SHOWN IN FEET AND DECIMALS THEREOF. SINCE HIS SURVEY INCESSION THE INCLUDE A TITLE SEARCH, THERE COULD BE EASEMENTS OR OTHER BNOUMBRANCES UPON THE LAND WHICH ARE NOT SHOWN ON THIS SURVEY PLAT. IF THESE BREED UIRED, PLEASE FURNISH THE NECESSARY INFORMATION. THE BEARINGS AND DISTANCES HOWN ON THE PLANE COORDINATES, SPC83, ZONE-OHIO BRITE. THIS SURVEY HAS BEEN RECORDED IN VOL. 28R PAGE 318 OF THE WILLIAMS COUNTY STATE PLANE RECORDED.

BRIAN M. WIELAND - REGISTERED SURVEYOR NO. 8286

DATE: 1-21-23 JOB: 23-012
WIFLAND SUPVEYING

WIELAND SURVEYING & ENGINEERING, LLC 14067 COUNTY ROAD 20 WEST UNITY, OH 43570 419-553-0112 VOICE brian@wielandsurveying.com