
PLAT OF SURVEY

A parcel of land situated in the Northeast Quarter of Section 20, Town 6 North, Range 2 East, Center Township, Williams County, Ohio. Located within the North and the East of the First Principal Meridian of the Original Land Subdivisions of Ohio.



SURVEY LEGEND

- Placed 5/8" Rebar w/ Cap
- X Found PK Nail
- • Point Established this Survey
 - O Found Iron Pin or Pipe
 - Found Railroad Spike

REFERENCE SURVEYS

Volume 15R Page 045 Volume 20R Page 084

GENERAL OCCUPATION NOTE:

No fences existed along the East, South or West boundaries of this property. All lines of occupation were either agricultural or lawn.

I hereby certify that I have surveyed the premises shown on the Platebove. All dimensions are shown in feet and decimals thereof. Since this survey does not include a this serich there could easements or other encumbrances upon the land which are not seewn on this survey plat. If these are required, please furnish the necessary information. The Bear and Distances shown on the Plat above are based on State Plane Coordinates, SPC83, Zone and North This survey has been

recorded in Volume 28R Page 555 of the Williams County Sureview ords

Brian M. Wieland - Ohio Registered Surveyor No. 8286

DATE: 3-5-2025

JOB: 25-037

WIELAND SURVEYING & ENGINEERING, LLC14067 County Road 20

14067 County Road 20 West Unity, OH 43570 419-553-0112 - Voice

brian@wielandsurveying.com