


PLAT & SURVEY

Survey made April 3 & 4 1961 for Robert B. Munday of Outlots 21 and 22 in the Northwest 1/4 of Section 8 Town 7 North, Range 4 East, Brady Township, William County, in the Village of West Unity, Ohio.

Scale 1" = 80'



Note:

A= Placed metal Surveyor's stake.
B= Cut cross in concrete walk

C= Cross at street line and Rail Road right of way intersection.

Recorded in Vol. 4V Page 99 Record of Surveys, in the County Engineer's Office, Bryan, Ohio.

I hereby certify the above Plat and Survey to be correct to the best of my knowledge.

M.E. Smith 99